



Repair Invoice

**5543 Tierra Gardens Lane
Carmichael, CA 95608**

DATE	Order NO.
5/5/2021	221123.4

SOLD TO
Brian Max Vaugan KF7MAX 1723 NE Lytle Bend, OR 97701 USA 541-706-1475

SHIP TO
Brian Max Vaugan KF7MAX 1723 NE Lytle Bend, OR 97701 USA maxv@horizonps.com

PAYMENT TYPE	REP	SHIP VIA	FOB
Credit Card	MA	USPS Priority	Origin

QTY	DESCRIPTION	RATE	AMOUNT
2	RigExpert AA-1000 Antenna Analyzer Equipment Repair SN 2383	65.00	130.00
1	RigExpert 50 Ohm Complete Return Loss Bridge Circuit	16.19	16.19T
1	RigExpert Detector circuit	25.32	25.32T
1	Return Shipping & Handling (Tracked and Insured for full value)	16.82	16.82
	Good Customer Discount (PNC credit for Detector circuit)	-25.32	-25.32
	TR - SWR Readings to infinity Trouble shoot and repair Return Loss Bridge circuit, Detector circuit and Mixer circuit. Replace components as necessary. Found excessive RF received at the front end. Recalibrate antenna analyzer at N-connector to factory standards. Checked and set all functions of analyzer. Updated firmware to v 4.18, added special QR feature. Check analyzer for HF/VHF compliant test jig, Test analyzer for non compliant UHF test jig (continuous sweep) setting markers at all ITU Region 2 bands for evaluation.		

Thank you for your business.	Subtotal	\$163.01
New equipment carries Manufacture warranties only. All RMA shipping and Handling costs are the responsibility of the customer. Shipping costs are non refundable. PNC does not make warranty of merchantability or fitness for any purpose. Non approved returns will not be accepted. A Restocking fee of 15% will be charged on all approved Returns. Returns must be in original packages and conditions. Returns after 7 days will receive store credit only.	Sales Tax (0.0%)	\$0.00
	Total	\$163.01